

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2013-00077708**

(Refer to vehicle by number)

ALL INVOLVED	G														Names & Addresses of Occupants - If Deceased, Date & Time of Death
	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code		
	83	84	85	86	87	88	89	90	91	92	93	94	95		
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 was turning left out of 1905 Route 88 (Camp Mall) to travel west on Route 88 when Vehicle 2 crashed into her. Vehicle 2 was traveling east on Route 88 when Vehicle 1 came out in front of her as she crashed into her, causing her to loose control and subsequently crash into a telephone pole (JC229BK).

Driver 1 stated she was turning left to on to Route 88 when she was immediately struck by Vehicle 2. Driver 2 stated Vehicle 1 just pulled out in front of her, she tried to avoid her but was unable to.

Investigation by this officer reveals that Driver 1 was inattentive, and failed to yield the right of way to Driver 2 which caused this crash.

Driver 1 complained of left hip pain, and pain to the left side of her head but refused medical treatment at the scene. Driver 2 complained of right wrist pain, right arm pain, right ankle pain, and pain to left side of her face and was transported to Brick Hospital by Brick Police EMS.

Driver 1 was issued a summons for careless driving 39:4-97 T-142965.

Frank

Mauro

207

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2013-00077708

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Frank

Mauro

207