

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2013-00078383**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #1 was traveling east on Route 88, behind a maroon conversion van. No plate given. The driver of vehicle

#1 believed the van was stopping on Route 88 to turn left into the Home Depot plaza. As vehicle #1 went to pass the minivan on the right side, the van pulled forward and cut in front of vehicle #1 to continue traveling east on Rt 88. Vehicle #1 pulled to the right to avoid crashing into the van. Vehicle #1 avoided the crash with the van but, struck a curb and fire hydrant in front of 1715 Rt 88.

JohnPawlowicz168

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2013-00078383

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



John

Pawlowicz

168