

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---**Case No: **2013-00015635**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 was backing from a parking stall in the parking lot of 1872 Route 88. Vehicle 2 was slowing in the parking lot behind vehicle 1. The crash occurred when vehicle 1 backed from the parking stall and impacted vehicle 2 in the right upper rear. On scene I observed no damage to vehicle 1, and damage to the right upper front of vehicle 2. No injuries were reported at the scene.

The driver of vehicle 1 was issued a summons for 39:3-10 and 39:4-97, T131818 and T131819. A licensed driver arrived to take control of the vehicle.

CharlesKelly241

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---





Case No: 2013-00015635

134 Crash Diagram (NOT TO SCALE)



Indicate
North

1872 Route 88



Charles

Kelly

241