

96	05	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		
97	01	1 Case Number		2013-00021010										10 Crash Occurred On: RT 88		11 Speed Limit		8 8		02		
98	01	2 Police Dept of		Brick PD										Code 01		At Intersection with		Road Name		Dir		118b
99	02	3 Station/Precinct		200.00										200.00		200.00		200.00		200.00		04
100	01	4 Date of Crash		dd		yy		5 Day of Week		Su M Tu W Th (F) Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured		119a		
101	02	23 Veh No		24 Policy No.		Y170210-9		25 Ins Code		042		53 Veh No		54 Policy No.		768-25-69		55 Ins Code		119b		
102	02	26 Driver's First Name		Initial		Last Name		29 Sex		F		56 Driver's First Name		Initial		Last Name		59 Sex		120		
103	02	27 Number and Street		51 Brandywine CT		30 Eyes		05		57 Number and Street		101 Kenneth PL		60 Eyes		06				121		
104	02	28 City		Brick		State		New Jersey		Zip		08724-		58 City		Brick		State		122		
105	03	31 State		NJ		32 Drivers License No		S8193		12476		53775		03 19 77		04 14		NJ		---		
106	02	35 Owner's First Name		Initial		Last Name		36 Number and Street		51 Brandywine CT		65 Owner's First Name		Initial		Last Name		66 Number and Street		123		
107	---	37 City		Brick		State		New Jersey		Zip		08724-		67 City		Brick		State		---		
108	01	38 Make		DODGE		39 Model		GRAND CARAVAN		40 Color		41 Year		1997		42 Plate No.		R59CDE		124		
109	01	44 VIN		1B4GP44R5VB420470		45 Expires		06 13		74 VIN		1FMDU84PX1UB05856		75 Expires		03 14				125		
110	01	46 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		☐ Impound		☐ Disabled		47 Authority		☒ Owner		☒ Driver		126		
111	01	48 Alcohol/Drug Test		Given: ☒ No		☐ Yes		☐ Refused		Type: ☐ Breath		☐ Blood		☐ Urine		Results: 0.00%		☐ Pending		127		
112	---	49 Hazardous Material		On Board		Spill		Name or Placard No.		134 Crash Diagram (NOT TO SCALE)		78 Alcohol/Drug Test		Given: ☒ No		☐ Yes		☐ Refused		128a		
113	---	50 Carrier No.		☐ USDOT		☐ Other *				80 Carrier No.		☐ USDOT		☐ Other *						128b		
114	---	51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name		81 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		128c		
115	04	52 Carrier name																		128d		
116	02	136 Damage To Other Property		None																129a		
117	---	137 Charge		☐ Multiple Charges				138 Summons No.		2		139 Charge		☐ Multiple Charges				140 Summons No.		129b		
118	---	141 Officer's Signature		Frank		Mauro		142 Badge No.		207		143 Reviewed By		Matthews		210		144 Case Status		129c		
119	---	145 Names & Addresses of Occupants - If Deceased, Date & Time of Death																		129d		
120	---	A		1		01		01		---		36		F		---		---		130		
121	---	B		1		03		01		---		11		F		---		---		131		
122	---	C		1		01		01		---		05		F		---		---		132		
123	---	D		2		01		01		---		45		F		---		---		133		
124	---	E																		---		

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2013-00021010**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 was making a left turn out of 1715 Route 88 (Oxford Plaza) to go west on Route 88. Vehicle 2 was traveling east on Route 88 when she crashed into Vehicle 1. Driver 1 stated she thought it was clear to make a left turn, as she awaited other traffic that was making a right turn into The Oxford Plaza. Driver 2 stated Vehicle 1 just pulled out in front of her, and she was unable to avoid the crash. Investigation by this officer reveals that Driver 1 was inattentive, and failed to yield right of way to Vehicle 2 which caused this crash. There were no reported injuries at the time of this report. While on scene I observed damage to both vehicles.

Frank

Mauro

207

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2013-00021010

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Frank

Mauro

207