

New Jersey Police Crash Investigation Report												Case Number 2020-00057732			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was stopped behind Vehicle #2 in the exit of the Walmart store (1872 Rt 88) leaving onto Jack Martin Blvd. Vehicle #1 started into traffic before Vehicle #2 and crashed into it's rear bumper.

The driver of Vehicle #1 stated that she believed Vehicle #2 was starting in traffic so she began to. When she realized that Vehicle #2 was still stopped, the driver of Vehicle #1 stated it was to late and she caused the crash.

The driver of Vehicle #2 stated that she was stopped at the exit waiting for oncoming traffic when Vehicle #1 crashed into her.

The crash looked to only cause a crack in the right tail light of Vehicle #2.

No injuries were reported on scene.


146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Paul J Catalina	Badge # 229	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00057732

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Jack Martin Blvd



Walmart Lot

Robert F Scelfo

Officer's Signature

189

Badge Number