

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2020-00058741					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Both Vehicles #1 and 2 were backing out of parking spaces across from one another, in the lot of the Walmart store (1872 Rt 88) and crashed.

Both drivers stated the other was at fault. A look of the surveillance footage showed that Vehicle #1 and Vehicle #2 both started to back out of their spaces at the same time with Vehicle #2 backing somewhat faster.

Neither driver seemed to have seen the other and crashed just passed the center of the aisle.

No injuries were reported on scene.

A video copy of the crash was entered into property.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Robert F Scelfo	189	Scott M Dierking	204	☐ Pending ☒ Complete


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00058741

144 Crash Diagram (NOT TO SCALE)

 Indicate North

Walmart Lot
1872 Rt 88



Robert F Scelfo

Officer's Signature

189

Badge Number