

New Jersey Police Crash Investigation Report												Case Number 2021-00002378			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was backing in lane 2 of the Walmart (1872 RT 88) parking lot and struck Vehicle 2 in the rear left bumper with its rear left bumper. Vehicle 1 received minor damage. Vehicle 2 received moderate damage. The passenger of Vehicle 2 stated he had neck pain, but did not want an ambulance on scene.

Driver 1 stated his vehicle was struck by Vehicle 2 when she backed out of a parking space.

Driver 2 stated she backed out of a parking space, stopped, was ready to travel forward, then her vehicle was struck.

I entered Walmart and observed the crash on surveillance camera footage. Vehicle 2 was observed stopped after backing out of a parking space while Vehicle 1 backed a distance and then struck Vehicle 2.

Based on my observations of the surveillance camera, I find Driver 1 at fault for unsafe backing. Driver 1 was issued traffic summons E21 000200 for careless driving (39:4-97).


146. Officer's Signature Christopher Robert Newlund	147. Badge # 285	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00002378

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Christopher Robert Newlund

285