

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2012-00056098**

(Refer to vehicle by number)

ALL INVOLVED	G														Names & Addresses of Occupants - If Deceased, Date & Time of Death
	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code		
	83	84	85	86	87	88	89	90	91	92	93	94	95		
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 2 was traveling at low speed in the rear parking lot of 1743 Route 88. Vehicle 1 was traveling behind Vehicle 2.

Both vehicles were traveling on a One Way Road, with One Way arrows painted on the roadway. Due to the size of Vehicle 2 and the narrow travel path, Driver 2 stayed to the left on the roadway as he attempted to park Vehicle 2 in a parking space. Driver 1, perceiving that Vehicle 2 was stopping, began to travel forward, passing Vehicle 2 on the right. As Vehicle 2 began to turn into the parking spot, it was struck on the passenger side by driver side mirror of Vehicle 1. No injuries were reported on scene. Vehicle 2 remained in the roadway, while Driver 1 parked Vehicle 1 in a parking space.

JohnTurrin199

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**


Code: **01-Municipal Police**

Station: **---**

Case No: **2012-00056098**

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



John

Turrin

199