

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2012-00050616**

(Refer to vehicle by number)

	G	Veh	Pos	Eject	Phys	Age	Sex	Loc	Type	Ref	Equip	Equip	Bag	Hosp	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		Occ	In/On		Cond			Inj	Inj	Med	Avail	Used	Depl	Code	
ALL INVOLVED		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
J															

135 Crash Description

Investigation at the scene revealed: Vehicle 2 was parked facing westbound in the parking lot of Home Depot located at 1722 Rt. 88. The driver of vehicle 2 had entered her vehicle, sat in the driver's seat, and started her engine so she could eat her lunch with the air conditioning on. Vehicle 1 was parked in the parking stalls located directly across from vehicle 2 facing eastbound. Vehicle 1 began to back out of his parking stall and tried to avoid the curb located directly to his right. In doing so he backed up too far and struck the rear of vehicle 2 with the lower right rear of his vehicle causing damage to both vehicles.

It should be noted no injuries were reported at this time and vehicle 1 was moved prior to my arrival. The driver of vehicle 1 was issued a summons for 39:4-97 (careless driving) on summons # T-126590.

Vehicle 2 occupant information:

Kathleen Marciniak

47 Central Avenue, Waretown, NJ 08758

Date of birth: 12/06/1959

New Jersey Drivers License#: M05554270062594

JosephLardieri251

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2012-00050616

134 Crash Diagram (NOT TO SCALE)

○ Indicate
North



1722 Rt. 88

Joseph

Lardieri

251