

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2012-00026011**

(Refer to vehicle by number)

	G	Veh	Pos	Eject	Phys	Age	Sex	Loc	Type	Ref	Equip	Equip	Bag	Hosp	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		Occ	In/On		Cond			Inj	Inj	Med	Avail	Used	Depl	Code	
ALL INVOLVED		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 2 legally parked facing southbound, parking lot of Walmart, 1872 Route 88. Vehicle traveling in an unknown direction in the parking lot of Walmart. Susan Rochette, driver of Vehicle 2 stated she went into Walmart at approximately 1800 hours. When Rochette came out at about 1920 hours, she found the passenger side rear of her vehicle had been struck. Investigation reveals it appears Vehicle 1 was backing southbound out of a parking space and struck the rear of Vehicle 2. Vehicle 1 then fled the area. Area checked negative for vehicle involved.

JohnBoronkas165

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police



Station: _____

Case No: 2012-00026011

134 Crash Diagram (NOT TO SCALE)



Walmart, 1872 Route 88



John

Boronkas

165