

96	05	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a									
97	01	1 Case Number		2012-00037596										10 Crash Occurred On: 1610 Route 88		11 Speed Limit						02									
98	01	2 Police Dept of		Brick PD										Code 01		12 Route No.		Suffix		13 Milepost		118b									
99	09	3 Station/Precinct		---										14		15		16		17 Cross Road Name		---									
100	---	4 Date of Crash		mm		dd		yy		5 Day of Week		Su M Tu W Th F Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured		119a									
101	02	23 Veh No		24 Policy No.		25 Ins Code		53 Veh No		54 Policy No.		55 Ins Code		19		20 Route/Name		21 Latitude		22 Longitude		119b									
102	01	26 Driver's First Name		Initial		Last Name		29 Sex		56 Driver's First Name		Initial		Last Name		59 Sex		60 Eyes				120									
103	01	27 Number and Street		14 Pompton Plains DR		30 Eyes		04		57 Number and Street		60 Eyes										121									
104	02	28 City		Brick		State		Zip		58 City		State		Zip								122									
105	06	31 State		NJ		32 Drivers License No		K2187 11500 61424		33 DOB mm dd yy		34 Expires mm yy		61 State		62 Drivers License No		63 DOB mm dd yy		64 Expires mm yy		---									
106	---	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		Last Name										123									
107	---	36 Number and Street		14 Pompton Plains DR		37 City		Brick		State		Zip		66 Number and Street		568 Davina CT		67 City		Lakewood		---									
108	01	38 Make		Chevrolet		39 Model		Malibu		40 Color		White		41 Year		1999		42 Plate No.		NKG37H		10									
109	01	44 VIN		1G1NE52J3X6214068		45 Expires		11 12		74 VIN		1N4AL11E36N354334		75 Expires		06 13						125									
110	01	46 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		47 Authority		☒ Owner		☐ Driver		☐ Police		76 Vehicle Removed To		☐ Driven		126									
111	01	48 Alcohol/Drug Test		Given: ☒ No		☐ Yes		☐ Refused		Type: ☐ Breath		☐ Blood		☐ Urine		Results: 0. %		☐ Pending				127									
112	---	49 Hazardous Material		On Board		Spill		Name or Placard No.		78 Alcohol/Drug Test		Given: ☐ No		☐ Yes		☐ Refused		Type: ☐ Breath		☐ Blood		128a									
113	---	50 Carrier No.		☐ USDOT		☐ Other *				79 Hazardous Material		On Board		Spill		Name or Placard No.		80 Carrier No.		☐ USDOT		128b									
114	---	51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		81 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name				128c									
115	---	52 Carrier name																				128d									
116	01	53		84		85		86		87		88		89		90		91		92		129a									
117	01	54		84		85		86		87		88		89		90		91		92		26									
136 Damage To Other Property None																						130									
137 Charge																						131									
138 Summons No.																						132									
139 Charge																						133									
140 Summons No.																						05									
141 Officer's Signature																						142 Badge No.		143 Reviewed By		144 Case Status					
Glenn Turner																						178		Gerling		148		☐ Pending ☒ Complete			
Names & Addresses of Occupants - If Deceased, Date & Time of Death																															
A 1 01 01 --- 69 F --- --- -- 09 04 --- --- Catherine Keenan 14 Pompton Plains DR Brick, New Jersey 08724-1335																															
B 1 03 01 --- 72 F --- --- -- 09 04 --- --- Ann Elizabeth Selvig 14532 Martha ST Sherman Oaks, California 91411-																															
C																															
D																															
E																															

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---**Case No: **2012-00037596**

(Refer to vehicle by number)

ALL INVOLVED	G														Names & Addresses of Occupants - If Deceased, Date & Time of Death
	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code		
	83	84	85	86	87	88	89	90	91	92	93	94	95		

135 Crash Description

Vehicle 1 traveling lot of 1610 Route 88 along the south side of the building. Vehicle 2 parked in the lot of 1610 Route 88 along the south side of the building facing north. Vehicle 1 attempted to park in the space directly to the right of Vehicle 2 and struck Vehicle 2 behind the rear passenger side wheel. Owner of Vehicle 2 was located while at the scene and no injuries were reported at the time this report was submitted.

Glenn

Turner

178

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**


Code: **01-Municipal Police**

Station: **---**

Case No: **2012-00037596**

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Glenn

Turner

178