

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2012-00039416**

(Refer to vehicle by number)

	G	Veh	Pos	Eject	Phys	Age	Sex	Loc	Type	Ref	Equip	Equip	Bag	Hosp	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		Occ	In/On		Cond			Inj	Inj	Med	Avail	Used	Depl	Code	
ALL INVOLVED		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #02 was unoccupied and parked in a parking space located in the lot of 1872 Route 88. Vehicle #01 was backing out of a parking space located directly to the rear of vehicle #02, in the parking lot of 1872 Route 88. Driver of vehicle #01 stated that he did not see vehicle #02 behind him as he was backing out, at which time he backed into vehicle #02. The right rear bumper of vehicle #01 crashed into the right rear bumper of vehicle #02, causing a collision. Vehicle #01 was moved prior to police arrival. No injuries were reported at the scene.

JenniferSutton239

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---


Case No: 2012-00039416

134 Crash Diagram (NOT TO SCALE)

 Indicate North



1872 Route 88



Jennifer

Sutton

239