

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2021-00018808					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

The driver of vehicle #1 stated she was backing out of a parking space in the parking lot of Walmart, 1872 Rt. 88, when she struck the rear of vehicle #2. She advised that vehicle #2 was backing out of a parking space directly behind her and they struck in the middle of the lot.

The driver of vehicle #2 stated she was backing out of a parking space. She stated that she pulled out of the space and began to move forward when vehicle #1 backed into her rear bumper.

Based on both of the driver's statements as well as observing the damage to both vehicles, it is my determination that both of the vehicle's appeared to be backing out at the same time and struck in the middle of the parking lot.

Minor damage to both vehicles. No injuries reported.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Keith Prendeville	223	Joshua A Jenssen	225	☐ Pending ☒ Complete



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00018808

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

parking lot of 1872 Rt.
88



Not To Scale

Keith Prendeville

223