

96	Page 1 of 4		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a																																		
05	1. Case Number				2021-00019009										10. Crash Occurred On: 1872 RT 88				11. Speed Limit		12. Route No.		13. Milepost		04																														
97	2. Police Dept. of				Code		Brick Police										01						01																																
98	3. Station/Precinct														14		15		16		18. Speed Limit		25																																
99	4. Date of Crash				5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured		19. To: 17. Cross Road Name/Route No.		20. Route Name/Route No.		22. Longitude		119b																																		
100a	mm		dd		yy		Su M Tu W		1 5 2 4		1 5 0 6				Ramp						120a																																		
01	0 3		2 0		2 1		Th F Sa		1 5 2 4		1 5 0 6										01																																		
100b	23. Veh. #				24. Policy No.				25. NJ Ins. Code				53. Veh. #				54. Policy No.				55. NJ Ins. Code				120b																														
04	01				4294-01-95-28				100				02				100 7898 D11 30D				962				—																														
101	26. Driver's First Name				Initial		Last Name		29. Sex		56. Driver's First Name				Initial		Last Name		59. Sex				121a																																
02	DANA				A		HAVENS		F		Juan Carlos						Valiente-Arias		M				01																																
102	27. Number & Street				1316 NORTHSTREAM PKWY										57. Number & Street				3732 MOUNT PLEASANT AVE												121b																								
103	28. City				State				Zip				58. City				State				Zip						—																												
104	Pt. Pleasant Boro				NJ				08742				BALTIMORE				MD				21224						—																												
02	30. Eyes		DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State				122																																
	0 2		D		0		-		NJ		0 2		D		-		-		MD				09																																
105	32. Driver's License Number				33. DOB				34. Expires				62. Driver's License Number				63. DOB				64. Expires						123																												
04	H 0 9 1 0				1 5 2 6 1				5 7 6 5 2				0 7 1 2 6 5				0 7 2 2				V 4 5 3				4 5 4 1 0				8 5 5 4				0 7 1 3 8 5				0 7 2 5				09														
106	35. Owner's First Name				Initial		Last Name		65. Owner's First Name										Initial		Last Name														124																				
—	☒ Same as Driver						DANA A HAVENS		☐ Same as Driver												DAVID MARTINEZ-RAMIREZ														11																				
107	36. Number & Street				1316 NORTHSTREAM PKWY										66. Number & Street				417 CEDARBRIDGE AVE												125																								
108	37. City				State				Zip				67. City				State				Zip						126a																												
04	Pt. Pleasant Boro				NJ				08742				LAKEWOOD				NJ				08701						26																												
109	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		73. State		126b																														
04	JEEP		Wrangler		SL		2005		WDN80X		NJ		Ford		Explorer		WT		2002		J35HUR		NJ		—																														
110	44. VIN				45. Expires				74. VIN				75. Expires																126c																										
01	1 J 4 F A 3 9 S 0 5 P 3 8 2 8 3 0				10/21				1 F M Z U 7 2 K 2 2 U D 0 3 5 5 1				04/20																—																										
111	46. Vehicle Removed to:														76. Vehicle Removed to:																126d																								
112	☒ Driven				☐ Towed Disabled		☐ Towed Disabled & Impounded		☐ Driven										☐ Towed Disabled		☐ Towed Disabled & Impounded														126e																				
—	☐ Left at Scene				☐ Towed Impounded				☒ Left at Scene										☐ Towed Impounded																26																				
113	47. Authority				☒ Owner										☐ Driver		☐ Police		77. Authority										☐ Owner		☐ Driver		☒ Police		127a																				
114	48. Alcohol Drug Test				Given: ☒ No ☐ Yes ☐ Refused										78. Alcohol Drug Test										Given: ☒ No ☐ Yes ☐ Refused										79. Hazardous Material										☒ None ☐ On Board ☐ Spill										127b
115	Type: ☐ Breath ☐ Blood ☐ Urine														Type: ☐ Breath ☐ Blood ☐ Urine																				Type: ☐ Breath ☐ Blood ☐ Urine																				127c
116	Results: 0. - %				☐ Pending				Results: 0. - %										☐ Pending				Results: 0. - %										☐ Pending				127d																		
04	50. Carrier No.				51. GVWR / GCWR (trucks & buses only)				80. Carrier No.				81. GVWR / GCWR (trucks & buses only)																127e																										
02	☐ USDOT				☒ None				☐ USDOT				☒ None				☐ USDOT										☒ None																26												
	☐ MC/MX								☐ MC/MX								☐ MC/MX																										—												
	52. Motor Carrier or Government Entity														82. Motor Carrier or Government Entity																128																								
	Number & Street														Number & Street																129																								
	City				State				Zip				City				State				Zip						130																												
																											11																												
	135. Damage to Other Property				☐ Yes (If Yes, describe)										☒ No												131																												
																											01																												
																											01																												
	Oper. 01				136. Charge				137. Summons No.				Oper. 02				138. Charge				139. Summons No.						133																												
					39:4-97				E21-0001955								39:3-4				E21-0001956						02																												
	Oper. —				140. Charge				141. Summons No.				Oper. —				142. Charge				143. Summons No.						134																												
																											02																												

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	—	55	F	—	—	—	11	04	—	—	DANA A HAVENS 1316 NORTHSTREAM PKWY Pt. Pleasant Boro NJ 08742
B	02	01	01	—	35	M	—	—	—	11	04	—	—	Juan Carlos Valiente-Arias 3732 MOUNT PLEASANT AVE BALTIMORE MD 21224
C	02	03	01	—	42	F	—	—	—	11	04	—	—	Alberta Sanchez 417 CEDARBRIDGE RD Lakewood NJ 08701
D	02	04	01	—	05	F	—	—	—	05	05	—	—	Selene Valiente 417 CEDARBRIDGE RD Lakewood NJ 08701

New Jersey Police Crash Investigation Report												Case Number 2021-00019009			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E	02	06	01	—	10	F	—	—	—	11	04	—	—	Briseda Valiente 417 CEDARBRIDGE RD Lakewood NJ 80701		
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was driving west in the parking lot of Walmart (1872 Route 88) looking for a parking space. Vehicle 2 was driving east in the parking lot of Walmart looking for a parking space. Vehicle 1 and Vehicle 2 both attempted to park in the same parking spot at the same time and crashed into each other.

In speaking with the driver of Vehicle 1, she stated she was stopped with her blinker on getting ready to pull into a spot where another vehicle was pulling out of. After the vehicle had pulled out of the parking spot, Vehicle 2 had come around the corner and without stopping tried to cut Vehicle 1 off. Driver of Vehicle 1 stated she then pulled into the parking spot. The driver of Vehicle 1 stated she did not think that she hit Vehicle 2 and that there was no crash.

In speaking with the driver of Vehicle 2, he stated he was stopped with his blinker on waiting for another vehicle to back out of a parking spot. Vehicle 2 stated he was already stopped and never saw Vehicle 1 stopped as the vehicle was backing out of the parking spot. After the Vehicle backed out of the parking spot, Vehicle 2 then began to turn into the parking spot when Vehicle 1 came out of nowhere and cut Vehicle 2 off. The driver of Vehicle 2 stopped to try and avoid the crash but could not stop in time. Vehicle 1's front driver side bumper

146. Officer's Signature Erik Ryan Talty	147. Badge # 303	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2021-00019009

145 Crash Description

struck Vehicle 2's passenger side bumper.

Witness 1 stated he was parked in the parking spot next to where the accident occurred and saw the entire crash happen. According to Witness 1, Vehicle 2 was stopped waiting to turn into the parking spot as another vehicle was backing out. As Vehicle 2 began to turn into the parking spot, Vehicle 1 came out of nowhere and was driving fast according to the witness. Witness 1 stated that he could hear the crash and that Vehicle 1 sped up to try and beat Vehicle 2 to the parking spot.

Based on the statements made by both drivers, the witness, and the facts of the investigation, Driver 1 is at fault for the accident. Driver 1 was issued a summons for careless driving (39:4-97), and the driver of Vehicle 2 was given a summons for unregistered motor vehicle (39:3-4).

Erik Ryan Talty

Officer's Signature

303

Badge Number



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01


Station: Case No: 2021-00019009

144 Crash Diagram (NOT TO SCALE)

 Indicate North



Not To Scale



Erik Ryan Talty

Officer's Signature

303

Badge Number