

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept: Brick PD Code: 01-Municipal Police Station: --- Case No: 2011-00052809
---	--

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
F															
G															
H															
I															
J															

135 Crash Description

On 09-17-2011 at 1425 hrs. while on routine patrol I observed a black pickup truck in the parking lot of 1832 Rt 88 .

I spoke with the driver Brian Naysmith who stated he was driving from 2217 Rt 88 and his vehicle was overheating.

At that time I observed heavy front damage to Naysmith's vehicle. upon inspection I observed fresh damage with bare steel and white paint transfer to the right side of the hood. A trail of engine coolant came from the intersection of Rt 88 and Post Rd. Specifically the left lane of Rt 88 approximate 100' from the intersection. It appears Naysmith then moved the vehicle into 1832 Rt 88 parking lot. Naysmith continued to advise me he was not in an accident.

Naysmith was issued summonses 39:4-129b #T-119161, 39:4-130 #T-119162, and 39:6B-2 #T-119163

Naysmith's vehicle was impounded for uninsured.

* Box 105 type of accident is unknown at this time.

RobertKoch170

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**


Code: **01-Municipal Police**

Station: **---**

Case No: **2011-00052809**

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Robert

Koch

170