

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2011-00059288**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #02 was occupied by the registered owner and parked in the side parking lot of 1890 Route 88. Vehicle #01 was attempting to park into the vacant parking space located next to the driver side of vehicle #02. While vehicle #01 pulled into the parking space, the front right bumper of vehicle #01 struck the rear left bumper of vehicle #02, causing a collision. Vehicles were not moved prior to police arrival. No injuries were reported at the scene.

JenniferSutton239

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**


Code: **01-Municipal Police**

Station: **---**



Case No: **2011-00059288**

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



1890 Route 88



Jennifer

Sutton

239