

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____

Case No: **2011-00069446**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Investigation reveals the following: Driver of vehicle 1 stated that while she was attempting to park in a parking spot at 1899 Rt.88, her foot slipped off the brake pedal of the vehicle and onto the gas pedal causing the vehicle to move forward and make contact with a concrete parking bumper and then a utility pole, (JC226BK), there was no damage to the pole or the parking bumper.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: _____

Case No: 2011-00069446

134 Crash Diagram (NOT TO SCALE)

 Indicate North

1899 Rt.88

