

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2012-00002668**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 and 2 parked in the parking lot of Home Depot (1722 Route 88) in the area between the main entrance and the garden center. Vehicle 1 was facing west and Vehicle 2 was facing east. Vehicle 2 backed from parking space into main travel lane. Vehicle 1 subsequently backed from parking space and struck Vehicle 2 along the driver's side near the rear wheel. Vehicle 1 suffered no visible damage and Vehicle 2 suffered damage to the rear quarter panel along the driver's side. Both vehicles were able to be driven away and no injuries were reported at the scene.

Glenn

Turner

178

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police


Station: _____

Case No: 2012-00002668

134 Crash Diagram (NOT TO SCALE)

 Indicate North

HOME
DEPOT
1722
ROUTE 88



Glenn Turner

Officer's Signature

178

Badge Number