

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2012-00010268**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 was traveling east through The Home Depot parking lot, stopped awaiting for another car to back out of a parking stall. Vehicle 2 was backing out of a parking stall when she crashed into Vehicle 1. Driver 2 stated she did not see Vehicle 1 as she was backing. Investigation by this officer reveals Driver 2 was inattentive and caused the crash. There were no reported injuries at the time of this report.

FrankMauro207

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police



Station: ---

Case No: 2012-00010268

134 Crash Diagram (NOT TO SCALE)

○ Indicate North

Home Depot



other traffic

Frank

Mauro

207