

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2010-00066654**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 was traveling behind Vehicle 2 westbound on Route 88. Vehicle 1 was passing Vehicle 2 on the right in the shoulder when she was struck by Vehicle 2. Driver 2 stated she was attempting to turn left off of Route 88 when she decided to turn right making contact with Vehicle 1 who was passing on the right side in on the shoulder. There were no reported injuries at the time of this report. I observed minor damage to both vehicles.

Frank

Mauro

207

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2010-00066654

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Frank

Mauro

207