

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2010-00032839**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Investigation at the scene revealed. V2 was legally parked in a parking space at 1722 Rt.88 (Home Depot) in the rear of the lot near the entrance / exit to Rt.70. V1 was traveling east through the parking lot as V2 began to back from his parking space. the rear of V2 collided with the right middle of V1.

No injuries were reported at this time and both vehicles were moved prior to my arrival.

MichaelMiller218

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---

Case No: 2010-00032839

134 Crash Diagram (NOT TO SCALE)



Indicate
North

Parking lot of Home Depot
(1722 Rt.88)



NOT TO SCALE



Michael

Miller

218