

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---**Case No: **2010-00006869**

(Refer to vehicle by number)

G		Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
ALL INVOLVED	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #1 was backing out of his parking spot in the Wal-Mart parking lot in an easterly direction. Vehicle #2 was backing up in a northerly direction in order to get to a parking spot. The driver of vehicle #2 did not see vehicle #1. As a result, the rear of vehicle #2 collided into the left side end of vehicle #1.

DonaldSmith133

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---


Case No: 2010-00006869

134 Crash Diagram (NOT TO SCALE)

☐ Indicate North



NOT TO SCALE



Donald Smith

Officer's Signature

133

Badge Number