

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2009-00049423**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Driver of Vehicle 01 stated she was backing out of a parking space at 1872 Rt 88, Walmart, when she struck Vehicle 02 backing out of a parking space on the opposite side at the same time. Driver of Vehicle 02 stated the same. Both Vehicles moved prior to Police arrival.

RobertKoch170

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2009-00049423


134 Crash Diagram (NOT TO SCALE)

○ Indicate North



1872 Rt88 WAL-MART

WAL-MART
Parking Lot



NOT TO SCALE

Robert

Koch

170