

96	Page 1 of 3	Fatal	New Jersey Police Crash Investigation Report										Reportable	Non-Reportable	Change Report					
97	1 Case Number		2009-00042796										10 Crash Occurred On:		1759 ROUTE 88		11 Speed Limit			118a
98	2 Police Dept of		Code		At Intersection with		Road Name		Dir		12 Route No.		Suffix		13 Milepost		18 Speed Limit		25	
01	Brick PD		01		Feet		N E of:		S W		14		15		16		17 Cross Road Name		51	
99	3 Station/Precinct		4 Date of Crash		5 Day of Week		6 Time		7 Municipality Code		8 Total Killed		9 Total Injured		19 Ramp		20 Route/Name		119a	
09			mm dd yy		Su M Tu W Th F Sa		(use 2400 hrs)								To: From:				---	
01			08 26 09				1 6 3 5		1506		--		--						119b	
101	23 Veh No		24 Policy No.		25 Ins Code		53 Veh No		54 Policy No.		55 Ins Code									
02	1		4096728722		100															
102	26 Driver's First Name		Initial		Last Name		29 Sex		56 Driver's First Name		Initial		Last Name		59 Sex				01	
01	Jean M McBride						F												121	
103	27 Number and Street		30 Eyes		57 Number and Street		60 Eyes												---	
01	562 Challenger WAY		06																	
104	28 City		State		Zip		58 City		State		Zip									
01	Jackson		New Jersey		08527-															
105	31 State		32 Drivers License No		33 DOB		34 Expires		61 State		62 Drivers License No		63 DOB		64 Expires				122	
11	NJ		M1126 39274 58716		08 24 71		05 13												---	
106	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		Last Name								123	
---	Same As Driver						Same As Driver												---	
107	36 Number and Street		66 Number and Street																124	
01	562 Challenger WAY																		09	
108	37 City		State		Zip		67 City		State		Zip								125	
---	Jackson		New Jersey		08527-														---	
109	38 Make		39 Model		40 Color		41 Year		42 Plate No.		43 State		68 Make		69 Model		70 Color		126	
---	TOYOTA		Yaris		White		2009		B181318		NJ								04	
110	44 VIN		45 Expires		74 VIN		75 Expires												127	
01	JTDJT903095261431		09 09																---	
111	46 Vehicle Removed To		47 Authority		76 Vehicle Removed To		77 Authority												128a	
---	Driven Left at Scene Towed		Impound Disabled		Driven Left at Scene Towed		Impound Disabled												---	
112	48 Alcohol/Drug Test		134 Crash Diagram (NOT TO SCALE)		78 Alcohol/Drug Test														128b	
---	Given: No Yes Refused		Indicate North		Given: No Yes Refused														55	
113	Type: Breath Blood Urine				Type: Breath Blood Urine														128c	
---	Results: 0 % Pending				Results: 0 % Pending														---	
114	49 Hazardous Material		Name or Placard No.		79 Hazardous Material		Name or Placard No.												128d	
---	On Board Spill				On Board Spill														---	
115	50 Carrier No.		USDOT Other *		80 Carrier No.		USDOT Other *												129a	
---																			---	
116	51 Commercial Vehicle Weight		52 Carrier name		81 Commercial Vehicle Weight		82 Carrier name												129b	
04	≤ 10,000 lbs				≤ 10,000 lbs														---	
---	10,001 - 26,000 lbs				10,001 - 26,000 lbs														129c	
117	≥ 26,001 lbs				≥ 26,001 lbs														---	
---																			129d	
130	136 Damage To Other Property		None																10	
131	Oper.		137 Charge		Multiple Charges		138 Summons No.		Oper.		139 Charge		Multiple Charges		140 Summons No.				10	
---	1								2										---	
132	141 Officer's Signature		142 Badge No.		143 Reviewed By		Badge No.		144 Case Status										---	
---					Pedersen		160		Pending Complete										---	
133	83		84		85		86		87		88		89		90		91		Names & Addresses of Occupants - If Deceased, Date & Time of Death	
A	1		01		01		---		38		F		---		---		04 04		Jean M McBride	
B																			562 Challenger WAY Jackson, New Jersey 08527-	
C																				
D																				
E																				

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2009-00042796**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #1 was parking her vehicle in a parking spot in the rear of the Laurelton plaza when the front of the vehicle fell into a Drainage basin that was located in the front portion of the parking spot. It is uncertain if the drainage grate was off and in the basin or the grate fell in when the vehicle drove over it.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: _____

Case No: 2009-00042796

134 Crash Diagram (NOT TO SCALE)



1759 Rt 88

