

96	04	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a																									
97	01	1 Case Number		2009-00044576										10 Crash Occurred On:		1872 Route 88		11 Speed Limit				118b																									
98	01	2 Police Dept of		Brick PD										Code		01		12 Route No.		Suffix		13 Milepost	18 Speed Limit	13																							
99	09	3 Station/Precinct												14		15		16		17 Cross Road Name		19 To: 20 From:		21 Latitude	22 Longitude	119a																					
100	01	4 Date of Crash		dd		yy		5 Day of Week		Su M Tu W Th F Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured						119b																							
101	02	23 Veh No		24 Policy No.				25 Ins Code				53 Veh No		54 Policy No.		55 Ins Code								120																							
102	01	26 Driver's First Name		Initial		Last Name		29 Sex				56 Driver's First Name		Initial		Last Name		59 Sex						121																							
103	01	27 Number and Street						30 Eyes				57 Number and Street						60 Eyes						---																							
104	02	28 City		State		Zip		58 City		State		Zip												---																							
105	02	31 State		32 Drivers License No				33 DOB mm dd yy		34 Expires mm yy		61 State		62 Drivers License No				63 DOB mm dd yy		64 Expires mm yy				122																							
106	---	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		Last Name						66 Number and Street		3006 Herbertsville RD				123																							
107	---	36 Number and Street						66 Number and Street										67 City		State		Zip		124																							
108	---	37 City		State		Zip		67 City		State		Zip						68 Make		69 Model		70 Color		71 Year	72 Plate No.	73 State																					
109	01	38 Make		39 Model		40 Color		41 Year		42 Plate No.		43 State		68 Make		69 Model		70 Color		71 Year		72 Plate No.		73 State																							
110	---	44 VIN						45 Expires				74 VIN						75 Expires																													
111	01	46 Vehicle Removed To		☐ Driven ☐ Left at Scene ☐ Towed		47 Authority		☐ Owner ☐ Driver ☐ Police				76 Vehicle Removed To		☒ Driven ☐ Left at Scene ☐ Towed		77 Authority		☐ Owner ☒ Driver ☐ Police																													
112	---	48 Alcohol/Drug Test		Given: ☐ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending				78 Alcohol/Drug Test		Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending																													
113	---	49 Hazardous Material		On Board ☐ Spill ☐		Name or Placard No.						79 Hazardous Material		On Board ☐ Spill ☐		Name or Placard No.																															
114	---	50 Carrier No.		☐ USDOT ☐ Other *								80 Carrier No.		☐ USDOT ☐ Other *																																	
115	---	51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs								81 Commercial Vehicle Weight		☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs																																	
116	---	52 Carrier name										82 Carrier name																																			
117	---																																														
134 Crash Diagram (NOT TO SCALE)																								136 Damage To Other Property		None		Oper. 1		137 Charge		☐ Multiple Charges		138 Summons No.		Oper. 2		139 Charge		☐ Multiple Charges		140 Summons No.					
141 Officer's Signature												142 Badge No.												143 Reviewed By												144 Case Status											
Jennifer Sutton												239																								☐ Pending ☒ Complete											
Names & Addresses of Occupants - If Deceased, Date & Time of Death																																															
Hit and Run																																															

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2009-00044576**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

V2 was unoccupied and parked in a parking space at Walmart, located at 1872 Route 88. When the driver of V2, Jennifer Cittadino G47153957360875, returned to her vehicle, she found damage to the rear driver side panel of her vehicle. The damage left a black mark which appeared to be from V1's tire or bumper, along with a light colored paint mark above it. The vehicle that was parked next to her did not have any damage to it and was darker in color. An area check for any lighter colored vehicles with possible front end damage was negative. The security department of Walmart checked their surveillance video of the parking lot with negative results. The lens of the camera that was facing towards V2 was damaged and was unable to show a clear picture. V2 was not moved prior to police arrival.

JenniferSutton239

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: _____

Case No: 2009-00044576

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Walmart
1872 Route 88

Jennifer

Sutton

239