

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: Brick PD Code: 01-Municipal Police

Motor Vehicle Crash Description

Station: _____ Case No: 2009-00009600

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #1 was plowing snow in the WalMart parking lot at 1872 Rt88. Vehicle #2 was parked in row 2 in the WalMart parking lot. While vehicle #1 was backing up, driver #1 stated he misjudged whereabouts of vehicle #2 and collided into the rear of vehicle #2.

AnthonyZurica242

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police


Station: _____

Case No: 2009-00009600

134 Crash Diagram (NOT TO SCALE)

○ Indicate North

Snow Plow



NOT TO SCALE

Anthony

Zurica

242