

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2009-00013063**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle #1 was parked in the Wal-mart parking lot (1872 Route 88) in row 7. Vehicle #2 was parked in the Wal-mart parking lot in row 6. Vehicle #2 backed out of the marked parking space after observing that there was no traffic behind her vehicle. The driver of vehicle #2 advised me that she exited her parking space and stopped her vehicle, before putting her vehicle into drive. She advised me that she was struck by vehicle #1, which had exited a parking space in row 7. The driver of vehicle #1 stated that she did not see that vehicle #2 was directly behind her vehicle as she backed out. Vehicle #1 struck the driver's side (rear end) of vehicle #2 and caused minor damage. No injuries were reported and both vehicles were moved prior to my arrival.

JosephFarnkopf173

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**

Code: **01-Municipal Police**

Motor Vehicle Crash Diagram

Station:

Case No: 2009-00013063

134 Crash Diagram (NOT TO SCALE)

○ Indicate North

Wal-mart

1872 Route 88

Row 6

Row 7

NOT TO SCALE

Joseph

Farnkopf

173