

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---**Case No: **2009-00016422**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
	83	84	85	86	87	88	89	90	91	92	93	94	95		
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 Route 88 W/B, stopped in traffic. Vehicle 2 stopped directly behind vehicle 1. Vehicle 3 slowing directly behind vehicle 2. Vehicle 3 did not come to a stop and collided in to the rear of vehicle 2. The impact caused vehicle 2 to move forward and collide into the rear of vehicle 1. Driver 3 stated she thought she was stopped prior to the collision and does not know how she collided into the rear of vehicle 2.

StevenTillberg205

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police


Station: ---

Case No: 2009-00016422

134 Crash Diagram (NOT TO SCALE)



Indicate
North



Steven

Tillberg

205