

New Jersey Police Crash Investigation Report												Case Number 2017-00079547			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed the following: Vehicle # 1 was stopped at a stop sign on Lawrence Dr waiting to make a right turn onto Princeton Ave E/B. Pedalcycle # 2 was traveling W/B in the E/B bike lane going straight in the wrong direction. Vehicle # 1 started to make its right turn and it's front made contact with Pedalcycle # 2's front tire. Vehicle # 1 was not moved prior to police arrival and Pedalcycle # 2 had moved onto the sidewalk.

Driver of Vehicle # 1 stated "I was making a right turn onto Princeton Ave and the bike hit me. It was going the wrong way in the bike lane otherwise I would have seen him and stopped."

Pedalcyclist # 2 stated "I was riding my bike straight and then the mail truck hit me ."

#39 make of Vehicle # 1 is Utilimaster.

*Vehicle # 1 is self insured, it's a mail carrier's truck for the US Post Office. It does not have license plates on it, it has the numbers 0223585 on the front and back roof area.


146. Officer's Signature Vincenzo Rosa	147. Badge # 171	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00079547

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Vincenzo Rosa

Officer's Signature

171

Badge Number