

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00079597			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was making a left turn into parking lot of 307 Drum Point Road from Drum Point Road while towing a trailer. Vehicle 2 was traveling east on Drum Point Road in the area of 307 Drum Point Road. While making the left turn Vehicle 1 did not leave enough space to safely complete the turn, causing Vehicle 2 to strike the rear of the trailer being towed by Vehicle 1.

The Driver of Vehicle 1 stated he was making a left turn into the parking lot of 307 Drum Point Road and believed he had enough space to complete the turn before Vehicle 2 crossed his path. The Driver of Vehicle 1 stated he saw Vehicle 2 traveling east on Drum Point Road and that Vehicle 2 did not attempt to stop until the last moment before Vehicle 2 struck the rear of the trailer he was towing.

The Driver of Vehicle 2 stated she was traveling east on Drum Point Road in the area of 307 Drum Point Road, when she observed Vehicle 1 and the trailer it was towing make a left turn in front of her. The Driver of Vehicle 2 stated she applied the brakes and attempted to avoid striking the trailer being towed by Vehicle 1.

The trailer information for Vehicle 1 is the following: New Jersey Registration TTL42T. Vin 55nbe1822h1004539.

146. Officer's Signature Christopher R Joaquim	147. Badge # 271	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2017-00079597

145 Crash Description

registered to KH Landscapes Inc. 45 Port Road, Brick, NJ 08724. Insured by Palisades Insurance Company (017)
Policy #PAC00001080287.

Vehicle 1 was undamaged during the accident, the trailer had minor damage to the right rear corner. Vehicle 2
had minor damage to the front right corner of the bumper. Both vehicles were moved prior to police arrival.
Both vehicles were driven from the scene by their respected drivers. There was no reported injuries on scene.

Christopher R Joaquim


271

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: — Case No: 2017-00079597

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Christopher R Joaquim

271