

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00029951			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling north through the parking lot of 1872 Route 88, Walmart, directly in front of the store. Vehicle 1 was attempting to turn left from a parking lane to proceed south in the parking lot directly in front of the store. Vehicle 1 turned directly into vehicle 2, colliding with it head on.

Driver 2 stated she was traveling north in the parking lot of Walmart and was going to turn right down a parking lane. Driver 2 stated as she was about to turn vehicle 1 began to turn left out of the same parking lane. Driver 2 stated she stopped her vehicle and vehicle 1 drove directly into the front of her, colliding with her head on.

Driver 1 stated she was attempting to turn left from a parking lane to proceed south in the parking lot in front of Walmart and that she turned into vehicle 2. Driver 1 stated vehicle 2 was stopped in the parking lot and she did not know how she misjudged and turned into her.

I was able to review the video surveillance at Walmart an observed the following: Vehicle 2 was traveling north through the parking lot and began to turn right into a parking lane but stopped when vehicle 1 began

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer Glenn C Turner	Badge # 178	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: Case No: 2021-00029951

145 Crash Description

turning out of the same parking lane. Vehicle 1 was traveling through the parking lane and proceeded through a stop sign without stopping, making a left turn to proceed south in the parking lot. Vehicle 1 turned into the travel lane of vehicle 2 which was stopped at this time. Vehicle 1 collided head on with vehicle 2.

Investigation revealed that the cause of the crash was due to driver 1 making an improper turn into on coming traffic.

Michael A DeFluri

Officer's Signature

270


Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2021-00029951

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Walmart
1872 Route 88



Michael A DeFluri

Officer's Signature

270

Badge Number