

New Jersey Police Crash Investigation Report												Case Number 2021-00018355			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On March 17, 2021, I responded to a crash in the area of Route 70 and Route 88. Upon arrival, I observed Vehicle #1 and Vehicle #2 in the parking lot. Vehicle #1 had moderate but functional damage to the front of her vehicle. Vehicle #2 had minor damage to the rear of her vehicle.

Driver #1 explained vehicle #2 was past the yield sign and already began to merge into traffic, to go westbound on Route 70, when she stopped in the middle of the road. When she stopped in the middle of the road, she crash into the rear of vehicle #2.

Driver #2 explained they were slowing down to merge into traffic. When they got to the yield sign, vehicle #1 crashed into the rear of her vehicle causing minor damage.

There were no reported injuries at this time.

146. Officer's Signature John O Scott	147. Badge # 266	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2021-00018355

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE



John O Scott

Officer's Signature

266

Badge Number