

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2021-00029279					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was backing out of a parking stall spot located at 1872 Rt. 88 (Wal-Mart). Vehicle 2 while backing observed vehicle 1 backing out of a parking stall spot as well directly behind her. Vehicle 2 stopped backing up while vehicle 1 continued. Vehicle 1 struck the left lower rear portion of vehicle 2 with vehicle 1's left lower rear portion of the vehicle causing moderate/functional damage to vehicle 2. Per driver 2 vehicle 1 sustained no damage.

While speaking with driver 2, she stated she was backing out of a parking spot. While she was backing out she looked at her rear view camera and observed vehicle 1 backing out of the parking spot directly behind her vehicle. As she observed vehicle 1 backing out so she stopped backing out. Vehicle 1 continued to back up and struck her vehicle. At that time, she stated she exited her vehicle. Driver 1, a black male subject, exited his vehicle a burgundy/maroon in color Chevrolet SUV and stated you hit me give me your papers. Driver 2 stated she re-entered her vehicle to contact the police and vehicle 1 left the scene towards Jack Martin Blvd.

Due to vehicle 1 leaving the scene I was unable to speak with driver 1.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Mark M Catalina	263	Erik A Olsen	185	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01
Station: — Case No: 2021-00029279

145 Crash Description

Upon conclusion of my investigation on scene, I have determined vehicle 1 to be at fault. Vehicle 1 also failed to stay on scene to speak with officers. Driver 2 was unable to get a license plate number for vehicle 1 and the surrounding areas were negative for vehicles matching the description that driver 2 gave of vehicle 1.

Mark M Catalina

263



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00029279

144 Crash Diagram (NOT TO SCALE)



Wal-Mart
1872 Rt. 88



Not To Scale

Mark M Catalina

Officer's Signature

263

Badge Number