



| New Jersey Police<br>Crash Investigation Report |    |    |    |    |    |    |    |    |    |    |    | Case Number<br>2021-00020212 |    |                                                                                | Page 2 of 3 |  |
|-------------------------------------------------|----|----|----|----|----|----|----|----|----|----|----|------------------------------|----|--------------------------------------------------------------------------------|-------------|--|
|                                                 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94                           | 95 | Names & Addresses of Occupants<br><i>If Deceased, Date &amp; Time of Death</i> |             |  |
| E                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| F                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| G                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| H                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| I                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| J                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |

144. Crash Diagram

Show NORTH by Arrow  
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle two was traveling East on Rt88. Vehicle one was departing a parking lot in the area of Fort Street onto Rt 88. Vehicle one failed to stop prior to entering Rt 88 and struck vehicle two in the driver's side front door with the front bumper of vehicle one. After the impact driver one departed the area on Rt 88 traveling West. Driver two advised that she is not injured and believes that vehicle one came out of a parking lot in the area of Fort Street. After vehicle one struck vehicle two driver two lost control of vehicle two, but did not strike any other objects. Driver two refused medical attention. I observed a large puncture in the front driver's side door of vehicle two. Additionally the rear driver's side door of vehicle two sustained a dent. The front driver's side door of vehicle two would not function as designed as a result of the accident. Vehicle two was determined to be safe to drive despite the damage to the door. After speaking with driver two and examining the damage to vehicle two I determined that driver one is at fault. The area was checked for vehicle one but vehicle one could not be located. It should be noted that driver two was not able to obtain the license plate number of vehicle one and could only describe vehicle one as a smaller, dark, SUV. Vehicle two was driven from the scene.

|                                            |                     |                                   |                |                                                                                                   |
|--------------------------------------------|---------------------|-----------------------------------|----------------|---------------------------------------------------------------------------------------------------|
| 146. Officer's Signature<br>John M Gannaio | 147. Badge #<br>234 | 148. Reviewer<br>Jason R Shepherd | Badge #<br>167 | 149. Case Status<br><input type="checkbox"/> Pending <input checked="" type="checkbox"/> Complete |
|--------------------------------------------|---------------------|-----------------------------------|----------------|---------------------------------------------------------------------------------------------------|


New Jersey Police Crash Investigation Report  
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01

Station:        Case No: 2021-00020212

144 Crash Diagram (NOT TO SCALE)

○ Indicate  
North



John M Gannaio

Officer's Signature

234

Badge Number