

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00021327			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling east on Route 88. As Vehicle 1 was traveling straight on Route 88 Vehicle 2 which was approaching from behind impacted the rear of Vehicle 1. Vehicle 1 pulled off to the side of the road and Vehicle 2 fled the scene in an unknown direction.

Driver 1 advised he could not obtain a description of Vehicle 2 but he believed it was blue. Driver 1 stated vehicle 2 approached at a high rate of speed. The rear of Vehicle 1 had substantial damage and the entire tailgate was caved in with the rear windshield blown out.

The area checked negative for Vehicle 2.


146. Officer's Signature Michael Zolezi	147. Badge # 269	148. Reviewer —	Badge # —	149. Case Status ☒ Pending ☐ Complete
---	----------------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00021327

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael Zolezi

Officer's Signature

269

Badge Number