

96	Page 1 of 4 ☐ Fatal New Jersey Police Crash Investigation Report ☒ Reportable ☐ Non-Reportable ☐ Change Report		118a
05	1. Case Number 2021-00051004		06
97	2. Police Dept. of Brick Police Code 01		118b
98	3. Station/Precinct —		25
99	4. Date of Crash mm dd yy 07 29 21		119a
02	5. Day of Week Su M Tu W Th F Sa Th F Sa		25
100a	6. Time (use 2400 hrs.) mm hh 16 28		119b
01	7. Municipality Code 1506		120a
100b	8. Total Killed —		01
04	9. Total Injured —		120b
101	23. Veh. # 932998104		121a
02	24. Policy No. 134		121b
102	25. NJ Ins. Code 02		122
103	26. Driver's First Name Catherine Initial R Last Name Romito-Bederka 29. Sex F		01
05	27. Number & Street 11 LISA ROBYN CIR		123
104	28. City Lakewood State NJ Zip 08701		02
02	30. Eyes 04 DL Class D Restrictions T1 Endorsements — 31. State NJ		124
105	32. Driver's License Number R63501157958014		04
106	33. DOB mm dd yy 08 01 01		125
107	34. Expires mm yy 08 22		08
108	35. Owner's First Name ☒ Same as Driver Catherine R Romito-Bederka		126a
109	36. Number & Street 11 LISA ROBYN CIR		126b
110	37. City Lakewood State NJ Zip 08701		26
111	38. Make Nissan 39. Model Maxima 40. Color BK 41. Year 2007 42. Plate No. L92NZR 43. State NJ		126c
112	44. VIN 1N4BA41E77C866185 45. Expires 07/22		126d
113	46. Vehicle Removed to: Surfside Collision		126e
114	☐ Driven ☒ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded		26
115	47. Authority ☐ Owner ☐ Driver ☒ Police		127a
99	48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.00 % ☐ Pending		127b
116	49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class — Placard No. —		127c
04	50. Carrier No. ☐ USDOT — ☒ None ☐ MC/MX —		127d
04	51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		127e
117	52. Motor Carrier or Government Entity Walmart Transportation LLC		128
118	53. Veh. # 4594424		26
119	54. Policy No. 19445		129
120	55. NJ Ins. Code 02		02
121	56. Driver's First Name Jerry Initial S Last Name Carl 59. Sex M		130
122	57. Number & Street 1358 TREVORTON RD		131
123	58. City Coal Township State PA Zip 17866		10
124	59. Eyes 06 DL Class D Restrictions 1 Endorsements BT 61. State PA		10
125	62. Driver's License Number 18717693		133
126	63. DOB mm dd yy 10 07 59		04
127	64. Expires mm yy 10 23		134
128	65. Owner's First Name ☐ Same as Driver Walmart Transportation LLC		03
129	66. Number & Street 702 8TH ST MS-0555		
130	67. City Union Beach Borough State — Zip 07735		
131	68. Make INTL 69. Model Transtar 70. Color WT 71. Year 2020 72. Plate No. 3EB489 73. State OK		
132	74. VIN 3HSDZA4L5N534557 75. Expires 09/21		
133	76. Vehicle Removed to: —		
134	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded		
135	77. Authority ☐ Owner ☒ Driver ☐ Police		
136	78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.00 % ☐ Pending		
137	79. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class — Placard No. —		
138	80. Carrier No. ☒ USDOT 0063585 ☐ None ☐ MC/MX —		
139	81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☒ ≥ 26,001 lbs.		
140	82. Motor Carrier or Government Entity Walmart Transportation LLC		
141	83. Number & Street 702 8TH ST MS-0555		
142	84. City Union Beach Borough State — Zip 07735		
143	135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No		
144	Oper. — 136. Charge — 137. Summons No. —		
145	Oper. — 140. Charge — 141. Summons No. —		
146	Oper. — 142. Charge — 143. Summons No. —		
147	83 84 85 86 87 88 89 90 91 92 93 94 95		
148	Names & Addresses of Occupants If Deceased, Date & Time of Death		
149	A 01 01 01 — 19 F — — 11 04 — — Catherine Rose Romito-Bederka 11 LISA ROBYN CIR Lakewood NJ 08701		
150	B 02 01 01 — 61 M — — 11 04 — — Jerry Scott Carl 1358 TREVORTON RD Coal Township PA 17866		
151	C — — — — — — — — — — — —		
152	D — — — — — — — — — — — —		

New Jersey Police Crash Investigation Report												Case Number 2021-00051004			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling west on State Highway 88. Vehicle 2, a tractor trailer semi-truck, was traveling south on Center Street, Walmart Parking lot, approaching the stop sign for State Highway. Vehicle 2 entered into the roadway to make a right turn onto State Highway 88 in order to proceed west on it. Vehicle 1 swerved left, struck the left lower front portion of vehicle 2 with vehicle 1's right lower front causing moderate/functional damage to vehicle 2 and disabling damage to vehicle 1. Vehicle 1 came to rest in the east bound lane of travel's shoulder.

Driver 1 stated she was traveling west on State Highway 88. As she was approaching the intersection of Center Street, she observed vehicle 2 attempting to make a left turn onto State Highway 88. Driver 1 stated she stopped in her lane of travel and then vehicle 2 stopped in the lane of travel. Driver 1 attempted to pass vehicle 2 by crossing over the double yellow center lines. As she was attempting to pass vehicle 2, it began to move forward again striking the right lower front portion of her vehicle.

Driver 2 stated he was making a right turn to travel west on State Highway 88. Prior to him entering into the roadway he was stopped at the stop sign on Center Street. Driver 2 stated he made sure the roadway was clear

146. Officer's Signature Mark M Catalina	147. Badge # 263	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☒ Pending ☐ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2021-00051004

145 Crash Description

for him to pull onto State Highway 88 specifically stating he look left towards the traffic signal of Jack Martin Boulevard and it was red with no cars approaching. He started to pull onto State Highway 88 and the east bound lanes stopped for him in order for him to fully pull onto State Highway 88. At that time, vehicle 1 came speeding up and attempted to pass him in the opposite lanes of travel. Driver 2 stated his truck is equipped with an on board dash camera which I was not able to view.

No injuries were reported at the scene. Vehicle 1's vehicle was towed by D&L for Surfside Collision due to it being a safety issue to travel with the damage.

Upon conclusion of my investigation, I have determined vehicle 1 to be at fault for the motor vehicle crash. Based on driver 1's statements of her stopping to let vehicle 2 enter the roadway, then attempting to pass vehicle 2 by crossing over the double yellow center lines proves vehicle 1 yield right of way to vehicle 2. Vehicle 1 then attempted to go around vehicle 2 as vehicle 2 was completing the wide turn for the tractor trailer semi truck.

Mark M Catalina


263

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00051004

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Mark M Catalina

Officer's Signature

263

Badge Number