

96	Page 1 of 3		☐ Fatal		New Jersey Police Crash Investigation Report										☐ Reportable		☒ Non-Reportable		☐ Change Report		118a																				
02	1. Case Number 2020-00057732										10. Crash Occurred On: 1872 RT 88										11. Speed Limit - -		12. Route No. Suffix		13. Milepost		09														
97	2. Police Dept. of Brick Police										Code 01		Road Name Dir														02														
98	3. Station/Precinct												At Intersection with ☐ Feet ☐ Miles										☐ N ☐ E ☐ S ☐ W		18. Speed Limit - -		25														
99	4. Date of Crash mm dd yy 09 28 20										5. Day of Week Su Mo Tu We Th F Sa Mo		6. Time (use 2400 hrs.) 12 29		7. Municipality Code 1506		8. Total Killed -		9. Total Injured -		19. To: 17. Cross Road Name/Route No. Ramp From: -		21. Latitude 20 Route Name/Route No. 22. Longitude		119b																
100a	23. Veh. # 24. Policy No. 01 939029121										25. NJ Ins. Code 054		53. Veh. # 54. Policy No. 02 911755653										55. NJ Ins. Code 134		120a																
01	26. Driver's First Name Robin										Initial Last Name Mango		29. Sex F		56. Driver's First Name Alyson										Initial Last Name Rakocy		59. Sex F		120b												
101	27. Number & Street 483 SIXTH AVE										State Zip NJ 07071		57. Number & Street 357 OLYMPIC ST										State Zip NJ 08724		121a																
102	28. City Lyndhurst												58. City BRICK TOWNSHIP												121b																
103	30. Eyes DL Class Restrictions Endorsements 31. State 0 2 D 1 - - NJ										60. Eyes DL Class Restrictions Endorsements 61. State 0 5 D - - - - NJ										122																				
05	32. Driver's License Number M 0 4 2 5 6 5 9 7 3 5 1 5 7 2										33. DOB mm dd yy 01 18 57		34. Expires mm yy 01 22		62. Driver's License Number R 0 2 2 2 0 3 6 7 4 5 6 7 7 5										63. DOB mm dd yy 06 02 77		64. Expires mm yy 07 20		06												
104	35. Owner's First Name Same as Driver Joseph Mango										Initial Last Name		65. Owner's First Name Same as Driver Fusion Auto Finance LLC										Initial Last Name		123																
02	36. Number & Street 483 SIXTH AVE										State Zip NJ 07071		66. Number & Street 1320 TENNIS DR										State Zip TX 76022		08																
105	37. City Lyndhurst												67. City Bedford												124																
106	38. Make 39. Model 40. Color 41. Year 42. Plate No. 43. State Ford Explorer WT 1994 Y42MCA NJ										68. Make 69. Model 70. Color 71. Year 72. Plate No. 73. State JEEP Wrangler YL 2019 Y91LJD NJ										125																				
04	44. VIN 45. Expires 1 F M D U 3 4 X 6 R U D 2 4 8 0 0 12/20										74. VIN 75. Expires 1 C 4 G J X A N 0 K W 5 0 1 4 7 0 05/23										08																				
107	46. Vehicle Removed to: ☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded										76. Vehicle Removed to: ☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded										26																				
108	47. Authority ☐ Owner ☒ Driver ☐ Police										77. Authority ☐ Owner ☒ Driver ☐ Police										26																				
109	48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending										49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No. - - - -										78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending										79. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No. - - - -										126b
01	50. Carrier No. ☐ USDOT ☒ None										51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.										80. Carrier No. ☐ USDOT ☒ None										81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.										126c
110	52. Motor Carrier or Government Entity										82. Motor Carrier or Government Entity										126d																				
111	Number & Street										Number & Street										126e																				
01	City State Zip										City State Zip										127a																				
112	135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No																				127b																				
113	Oper. 136. Charge										137. Summons No.										Oper. 138. Charge										139. Summons No.										127c
114	Oper. 140. Charge										141. Summons No.										Oper. 142. Charge										143. Summons No.										127d
115																																									127e
116																																									128
02																																									26
117																																									129
02																																									130
																																									131
																																									05
																																									05
																																									133
																																									02
																																									134
																																									02
										Names & Addresses of Occupants If Deceased, Date & Time of Death																															
A										01 01 01 - 63 F - - - 11 04										Rubin Mangu 483 SIXTH AVE Lyndhurst NJ 07071																					
B										01 03 01 - 90 F - - - 11 04										Eleanor Donovan 233 BUCKINGHAM CT A Lakewood NJ 08701																					
C										02 01 01 - 43 F - - - 11 04										Alyson Rakocy 357 OLYMPIC ST BRICK TOWNSHIP NJ 08724																					
D																																									

New Jersey Police Crash Investigation Report												Case Number 2020-00057732			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was stopped behind Vehicle #2 in the exit of the Walmart store (1872 Rt 88) leaving onto Jack Martin Blvd. Vehicle #1 started into traffic before Vehicle #2 and crashed into it's rear bumper.

The driver of Vehicle #1 stated that she believed Vehicle #2 was starting in traffic so she began to. When she realized that Vehicle #2 was still stopped, the driver of Vehicle #1 stated it was to late and she caused the crash.

The driver of Vehicle #2 stated that she was stopped at the exit waiting for oncoming traffic when Vehicle #1 crashed into her.

The crash looked to only cause a crack in the right tail light of Vehicle #2.

No injuries were reported on scene.


146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Paul J Catalina	Badge # 229	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00057732

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Jack Martin Blvd



Walmart Lot

Robert F Scelfo

Officer's Signature

189

Badge Number