

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00050552			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle # 1 collided with Vehicle #2 in a rear end crash while traveling eastbound on RT 88 in the right lane near the intersection of RT 88 and Olden Street.

Driver of Vehicle #1 stated she was traveling eastbound on RT 88 in the right lane when Vehicle #2 stopped in front of her at the light. Driver #1 stated she attempted to stop in time to avoid the crash but was unsuccessful. Driver #1 stated her front license plate tapped Vehicle #2. Vehicle #1 had minor damage to the front end.

Driver of Vehicle #2 stated he was traveling eastbound on RT 88 in the right lane prior to coming to a complete stop at the traffic signal at the intersection of RT 88 and Olden Street. Driver #1 stated he was stopped at the light for a few seconds before Vehicle #1 struck his vehicle in the rear. Vehicle #2 sustained minor damage to the rear end.

Based on my observations and statements made by both parties I found the Driver of Vehicle #1 at fault for the crash for following too closely.


146. Officer's Signature Frank James Giambona	147. Badge # 290	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00050552

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Frank James Giambona

290