

New Jersey Police Crash Investigation Report												Case Number 2020-00068204			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed, Vehicle #1 was traveling West on Rt 88. Vehicle #2 was stopped in traffic on
Rt 88 Westbound.

The Driver of Vehicle #1 explained that he was traveling West on Rt 88 and took his eyes off of traffic in front
of him to look to his right, at an active construction site. When the Driver of Vehicle #1 looked back at the
roadway, he observed Vehicle #2 stopped in traffic. The Driver of Vehicle #1 attempted to stop, but struck the
rear of Vehicle #2.

The Driver of Vehicle #2 stated that he was stopped in traffic and was struck from behind by Vehicle #1.

I find the Driver of Vehicle #1 to be at fault due to driver inattention.

*Vehicle #2 (Marked Police Vehicle 128) Insurance Info:
Ocean County Municipal Joint Insurance Fund
PERMA Inc.

146. Officer's Signature James L Bartolucci	147. Badge # 183	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00068204

145 Crash Description

9 Campus Dr, Suite 216

Parsippany NJ 07054

James L Bartolucci

183

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram



Police Dept: Brick Police Code: 01

Station: Case No: 2020-00068204

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Rt 88



James L Bartolucci

Officer's Signature

183

Badge Number