

New Jersey Police Crash Investigation Report												Case Number 2020-00061049			Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On Rt 70 east in the right turn lane for Rt 88 east Vehicle 01 struck the rear of Vehicle 02.

Driver of Vehicle 02 stated she was on Rt 70 east in the right turn lane for Rt 88 east and while approaching Rt 88 she observed a blue truck partially in her lane. Driver of Vehicle 02 stated she swerved to the right and applied the brakes when struck in the rear by Vehicle 01.

Driver of Vehicle 01 stated he was traveling east on Rt 70 in the right turn lane for Rt 88 east when he observed Vehicle 02 swerve to the right and suddenly stop. Driver of Vehicle 01 stated he could not stop in time striking the right rear of Vehicle 02 with left front.

My investigation revealed Vehicle 01 was at fault.

Both Vehicles were moved prior to Police arrival.

146. Officer's Signature Robert Koch	147. Badge # 170	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2020-00061049

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



Robert Koch

Officer's Signature

170

Badge Number