

New Jersey Police Crash Investigation Report												Case Number 2020-00061493			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene indicated the following: Vehicle 1 was backing out of the driveway of Van Holten's Chocolates located 1893 Route 88 onto Barb Lane. Vehicle 2 traveled north on Barb Lane approaching Jack Martin Boulevard. Vehicle 1 backed into vehicle 2 which caused minor damage to both vehicles.

I spoke to driver 1 at the scene. He said he was backing out and didn't see the vehicle behind him.

Based on statements made and damage, Driver 1 was determined to be at fault.

146. Officer's Signature Anthony William Chadwick	147. Badge # 281	148. Reviewer Daniel Waleski	Badge # 157	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2020-00061493

144 Crash Diagram (NOT TO SCALE)



Anthony William Chadwick

Officer's Signature

281

Badge Number