

96	Page 1 of 4		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a																														
05	1. Case Number				2020-00074874										11. Speed Limit				40		12. Route No.		13. Milepost		02																										
97	2. Police Dept. of				Code		10. Crash Occurred On: RT 88										W		Dir		18. Speed Limit		17																												
01	Brick Police				01		Road Name										of: Park Avenue						119a																												
98	3. Station/Precinct						50										14		15		16		119b																												
01							☐ At Intersection with										☐ N ☐ E		☐ S ☒ W				119c																												
99	4. Date of Crash				5. Day of Week		6. Time (use 2400 hrs.)				7. Municipality Code		8. Total Killed		9. Total Injured		19. To: 17. Cross Road Name/Route No.				21. Latitude		22. Longitude		120a																										
02	mm dd yy				Su M Tu W Th F Sa		07 46				1506						Ramp From: -								01																										
100a	122				123		124				125		126		127		128				129		130		120b																										
01	23. Veh. #				24. Policy No.		939684977										25. NJ Ins. Code		054		53. Veh. #				54. Policy No.		55. NJ Ins. Code		121a																						
04	01																												121b																						
101	26. Driver's First Name				Initial		Last Name		29. Sex										56. Driver's First Name		Initial		Last Name		59. Sex										122																
02	MOUNIR				A		YACOB		M																										01																
102	27. Number & Street				16 EARL CT																57. Number & Street																				123										
01	28. City				State		Zip		08527										58. City				State		Zip																		124								
01	Jackson Township																																										04								
103	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State																		05												
01	01				D		1				NJ																												52												
104	32. Driver's License Number				33. DOB				34. Expires				62. Driver's License Number				63. DOB				64. Expires																				52										
11	Y0077				56861				01601				010560				1121																												52						
105	35. Owner's First Name				Initial		Last Name		65. Owner's First Name										Initial		Last Name																		52												
01	Same as Driver						GIHANE SAID		Same as Driver																														52												
106	36. Number & Street				16 EARL CT																66. Number & Street																				52										
01	37. City				State		Zip		08527										67. City				State		Zip																		52								
01	Jackson Township																																										52								
107	38. Make				39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make				69. Model		70. Color		71. Year		72. Plate No.		73. State																		52						
01	Lexus				RX300		BK		2013		E86CNJ		NJ																																52						
108	44. VIN				45. Expires										74. VIN				75. Expires																										52						
01	J T J B K 1 B A 2 D 2 4 5 3 5 1 2				09/21																																								52						
109	46. Vehicle Removed to:				Glen's Towing																76. Vehicle Removed to:																				52										
110	☐ Driven				☒ Towed Disabled		☐ Towed Disabled & Impounded		☐ Driven										☐ Towed Disabled		☐ Towed Disabled & Impounded																		52												
01	☐ Left at Scene				☐ Towed Impounded				☐ Left at Scene										☐ Towed Impounded																				52												
111	47. Authority				☐ Owner		☒ Driver		☐ Police		77. Authority										☐ Owner		☐ Driver		☐ Police																		52								
112	48. Alcohol Drug Test				Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0.00 % ☐ Pending		49. Hazardous Material		☒ None ☐ On Board ☐ Spill		78. Alcohol Drug Test		Given: ☐ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0.00 % ☐ Pending		79. Hazardous Material		☐ None ☐ On Board ☐ Spill																		52								
113	50. Carrier No.				☐ USDOT		☒ None		51. GVWR / GCWR (trucks & buses only)		☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.		80. Carrier No.				☐ USDOT		☒ None		81. GVWR / GCWR (trucks & buses only)		☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.																		52		
02	52. Motor Carrier or Government Entity																				82. Motor Carrier or Government Entity																				52										
114	Number & Street																				Number & Street																				52										
115	City				State		Zip												City				State		Zip																		52								
116	135. Damage to Other Property				☒ Yes (If Yes, describe)		☐ No		JCP&L .										137. Summons No.				Oper. 138. Charge		139. Summons No.																		52								
01	76 S MAIN ST, Akron, OH 44308																		1506-E20-4577																								52								
117	Two (2) JCP&L Utility Poles Damaged																																												52						
118	Oper. 136. Charge				39:4-97				Oper. 140. Charge										141. Summons No.		Oper. 142. Charge		143. Summons No.																		52										
01																																											52								
119	83				84		85		86		87		88		89		90		91		92		93		94		95		Names & Addresses of Occupants If Deceased, Date & Time of Death																52						
01	01				01		01		60		M		11		04		02		MOUNIR ATTIA YACOB																52																
01	16				EARL CT		Jackson Township		08527																																		52								
01																																																			52
01																																																			52
01																																																			52

New Jersey Police Crash Investigation Report												Case Number 2020-00074874			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a one vehicle crash into two fixed objects. The driver of vehicle 1 stated he was traveling west on Route 88 approaching Park Avenue. The driver of vehicle 1 initially stated an unknown vehicle traveling east on Route 88 came slightly crossed over the double yellow painted line in the roadway at which time, the driver of vehicle 1 stated he swerved to the right causing the upper right front side of vehicle 1 to crash into a utility pole (the JCP&L utility pole had no markings/identification number affixed to it) located in front of 1477 Route 88.

While investigating the crash scene, I observed a large debris field and significant damage to base of another/second utility pole approximately 100 feet east of the first pole (JCP&L utility pole#JC133BK) located on Route 88 W in front of 1469 Route 88. The damage to the second utility pole, as well as, the vehicle debris field in the area of the second utility pole evidently clear that vehicle 1 had crashed into said pole. It should be noted that the driver of vehicle 1 never made any statements during the initial investigation that he had in fact crashed into the second utility pole.

After speaking with the driver of vehicle 1 further, he admitted that he was utilizing his cell phone in attempts

146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Reviewer Frank W Mauro	Badge # 207	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: — Case No: 2020-00074874

145 Crash Description

to dial a phone number in said phone. As a result of the driver of vehicle 1 utilizing his cell phone and not paying attention to the roadway in front of him as he traveled west on Route 88, vehicle 1 ran off the road to the left causing the upper right front side of vehicle 1 to crash into a utility pole (JCP&L utility pole#JC133BK) located in front of 1469 Route 88.

After crashing into the aforementioned utility pole, vehicle 1 continued traveling west in the shoulder area on Route 88 for approximately 100 feet. After traveling said distance in the shoulder area, the upper right front side of vehicle 1 crashed into a second utility pole (the aforementioned JCP&L utility pole with no markings affixed to it) at which time it came to rest in the shoulder area in front of 1477 Route 88. Based on the sequence of events of the crash, the damage to both utility poles, and the distance between the two utility poles that vehicle 1 crashed into, doesn't support the driver of vehicle 1's statement about an unidentified vehicle (traveling east on Route 88) crossing over the double yellow lines which forced the driver of vehicle 1 to swerve to the right.

Vehicle 1 sustained significant damage and was towed from the scene by Glen's Towing Company. The driver of vehicle 1 complained of no injuries at the scene. The two utility poles sustained significant damage at the base of both poles. Personnel from JCP&L (JCP&L Point Pleasant Beach, NJ Office/Garage) was contacted and responded to the scene to assess the damage sustained to both utility poles.

The driver of vehicle 1 is at fault for the crash and was issued a motor vehicle summons for 39:4-97 (1506-E20-4577), 39:4-97.3 (1506-E20-4578), and 39:4-88B (1506-E20-4579).

Thomas P Caulfield


235

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00074874

144 Crash Diagram (NOT TO SCALE)


○ Indicate
North



Not To Scale

Route
88

Park Avenue



Thomas P Caulfield

Officer's Signature

235

Badge Number