

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00074914			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle, left turn crash. Vehicle 1 was stopped for a marked stop sign in the Home Depot parking lot, 1722 Route 88, awaiting to turn left onto Olden Street. Vehicle 2 was traveling south on Olden Street in the left lane approaching the entrance/exit area for the Home Depot parking lot.

The driver of vehicle 1 stated the right lane southbound traffic on Olden Street was backed up and congested as he was awaiting to turn left out of said parking lot. While still stopped at the marked stop sign, an unknown vehicle (which was stopped in the right lane on Olden Street due to the traffic) waived/signaled to the driver of vehicle 1 to turn left onto Olden Street.

After being waived/signaled to turn, the driver of vehicle 1 proceeded to turn left out of the aforementioned parking lot and onto Olden Street. As vehicle 1 was turning left, it turned directly into the path of vehicle 2 who was traveling in the left lane on Olden Street going southbound. The aforementioned left lane where vehicle 2 was going straight ahead at the time did not have any traffic/congestion and wasn't backed up like the right lane was.

146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2020-00074914

145 Crash Description

As vehicle 1 proceeded to turn left onto Olden Street, the driver of vehicle 1 stated he did not see vehicle 2 traveling in the left lane during his turn. As a result of vehicle 1 turning directly into the path of vehicle 2, the front end of vehicle 2 crashed into the upper left front side of vehicle 1 causing damage to both vehicles.

No injuries were reported and both vehicles were driven from the scene. The driver of vehicle 1 is at fault for the crash.

Thomas P Caulfield

235

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00074914

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale



Thomas P Caulfield

Officer's Signature

235

Badge Number