

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2020-00025433					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was towing a trailer, traveling south on Clay Avenue and attempting to cross over Route 88. Vehicle 2 was traveling east on Route 88 approaching Clay Avenue. Vehicle 1 entered the intersection of Route 88 and was unable to fully cross through the intersection in time, in front of vehicle 2, and vehicle 2 subsequently collided with the trailer within the intersection.

Driver 1 stated he was stopped at the stop sign, south on Clay Avenue, at the intersection of Route 88. Driver 1 stated he did not observe any traffic on Route 88 and entered the intersection, attempting to pull straight across into the parking lot across the street, when he observed vehicle 2 traveling on Route 88 east towards him. Driver 1 stated he believed vehicle 2 was traveling at a high rate of speed and could hear vehicle 2 skid on the pavement prior to the collision with his trailer.

Driver 2 stated he was traveling east on Route 88 approaching Clay Avenue when vehicle 1 pulled out in front of him, attempting to cross the intersection into a parking lot. Driver 1 stated he attempted to stop but was unable to stop in time and he struck the trailer that vehicle 1 was towing.

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
--	----------------------------	--	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2020-00025433

145 Crash Description

A witness on scene provided a statement on a motor vehicle crash statement form that was consistent with the account of events depicted by driver 2.

Investigation revealed that the cause of the crash was due to driver 1's inattentiveness to the cross traffic on Route 88 and not ensuring the roadway was free and clear of traffic to safely make it completely through the intersection.

Trailer information: NJ registration TVZ49H. Make: MAT. Model: MAL. Expiration: 3/2020

Color: Green, VIN: 5ANCD14244R017063

Michael A DeFluri

Officer's Signature

270


Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00025433

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael A DeFluri

Officer's Signature

270

Badge Number