

PAGE 1 OF 3		New Jersey Police Crash Investigation Report		☒ Reportable		☐ Non-Reportable		☐ Change Report	
02	1 Case Number		10 Crash Occurred On:		11 Speed Limit		118a		
97	17-67697		LAKEWOOD ROAD		S 45		0009 - -		02
-	2 Police Dept of		At Intersection With		Road Name		12 Route No. Suffix 13 Milepost 18 Speed Limit		118b
98	TOMS RIVER POLICE DEPT 01		☐ Feet		N E of: LOMELL LN		40		119a
06	3 Station/Precinct		☐ Miles		S W		19 To 17 Cross Road Name		-
99	-		14 15		16		☐ NB ☐ EB ☐ SB ☐ WB		119b
02	4 Date of Crash		5 Day Of Week		6 Time (use 2400 hrs)		7 Municipality Code		119c
100a	12/02/17		SATURDAY		1809		1507 --		-
01	23 Veh #		24 Policy No.		25 NJ Ins. Code		53 Veh #		120a
100b	1		909805694		054		-		05
04	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp To Emergency ☐ Hit & Run		☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp To Emergency ☐ Hit & Run						120b
101	26 Driver's First Name		Initial		Last Name		29 Sex		121a
02	URIEL		-		BRUNO		M		-
01	27 Number & Street		57 Number & Street						121b
103	69 GLADNEY AVE		-						-
01	28 City		State		Zip		58 City		122
104	TOMS RIVER		NJ		08753		-		01
1	30 Eyes		DL Class		Restrictions		Endorsements		123
	02		D		-		-		-
105	32 Driver's License Number		33 DOB		34 Expires		62 Driver's License Number		124
11	B76737600005942		05/24/1994		12 19		-		04
106	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		125
-	☐ Same As Driver		FILIMON		BRUNO		☐ Same As Driver		-
107	36 Number & Street		66 Number & Street						126a
-	23 AMHERST RD		-						46
108	37 City		State		Zip		67 City		126b
01	MANCHESTER		NJ		08759		-		47
109	38 Make		39 Model		40 Color		41 Year		126c
-	NISS		ALT		BK		2013		-
110	44 VIN		45 Expires		74 VIN		75 Expires		127a
01	1N4AL3AP6DC181706		11 17		-		-		127b
111	46 Vehicle Removed To		76 Vehicle Removed To						127c
-	ACCURATE TOWING		-						-
112	☐ Driven ☐ Towed Disabled ☒ Towed Disabled & Impounded		☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded						127d
-	☐ Left At Scene ☐ Towed Impounded		☐ Left At Scene ☐ Towed Impounded						127e
113	47 Authority		77 Authority						127f
-	☐ Owner ☐ Driver ☒ Police		☐ Owner ☐ Driver ☐ Police						128
114	48 Alcohol/Drug Test		49 Hazardous Material		78 Alcohol/Drug Test		79 Hazardous Material		129
-	Given: ☐ No ☐ Yes ☒ Refused		☒ None ☐ On Board ☐ Spill		Given: ☐ No ☐ Yes ☐ Refused		☐ None ☐ On Board ☐ Spill		04
115	Type: ☐ Breath ☐ Blood ☐ Urine		-		Type: ☐ Breath ☐ Blood ☐ Urine		-		130
-	Results: 0. - % ☐ Pending		Hazard Class Placard No.		Results: 0. - % ☐ Pending		Hazard Class Placard No.		01
116	50 Carrier No.		51 GVWR/GCWR		80 Carrier No.		81 GVWR/GCWR		131
03	☐ USDOT - ☒ None		☐ Weight <= 10,000 lbs ☐ Weight 10,001-26,000 lbs ☐ Weight >= 26,001 lbs		☐ USDOT - ☒ None		☐ Weight <= 10,000 lbs ☐ Weight 10,001-26,000 lbs ☐ Weight >= 26,001 lbs		132
117	☐ MC/MX -				☐ MC/MX -				133
-	52 Motor Carrier or Government Entity		82 Motor Carrier or Government Entity						134
	-		-						135
	Number & Street		Number & Street						136
	-		-						137
	City		State		Zip		City		138
	-		-		-		-		139
	135 Damage To Other Property		☒ Yes (If Yes, describe) ☐ No						140
	GUARD RAIL THAT VEHICLE IMPACTED WITH WAS HEAVILY DAMAGED.								141
	Oper. 136 Charge		137 Summons. No.		Oper. 138 Charge		139 Summons. No.		142
	1 39:4-50		1507E17011007		1 39:4-96		1507E17011011		143
	Oper. 140 Charge		141 Summons. No.		Oper. 142 Charge		143 Summons. No.</		

**New Jersey Police
Crash Investigation Report**

Police Dept: **TOMS RIVER POLICE DEPT** Code: **01**
 Station: **-** Case No: **17-67697**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A														
L														
E														
I														
N														
V														
O														
L														
H														
V														
E														
I														
D														
J														

144 Crash Diagram (NOT TO SCALE)

See Crash Diagram

145 Crash Description/Narrative

Contact was made on scene with a witness Kenneth Hamilton. Kenneth informed me that he had just pulled out of the Home Depot parking lot and was driving behind vehicle 1 when he observed the following. Vehicle 1 was traveling south bound on Lakewood road and swerved right and sideswiped a guard rail on the side of the road. Vehicle 1 continued traveling southbound approaching the entrance ramp to the Garden State Parkway. Vehicle 1 was still traveling on the right shoulder and when it crossed the entrance ramp to the Garden State Parkway it impacted with the end of a guard rail on the side of Lakewood Road Southbound. Kenneth then observed a Hispanic male exit vehicle 1 and walk southbound. Contact was then made with the operator of vehicle 1, see the undersigned's investigation report for further details.

When asked, the operator of vehicle 1 stated that he had been drinking and he crashed. The operator would not state any further details relating to the crash.

I observed damage to rear passenger side quarter panel of vehicle 1 and heavy damage to the passenger's side of the front bumper of vehicle 1.

146 Officer's Signature

ELWOOD, T.

147 Badge #

0406

148 Reviewer

MOONEY, E.

Badge #

335

149 Case Status


☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: TOMS RIVER POLICE DEPT Code: 01
Station: - Case No: 17-67697

144 Crash Diagram (NOT TO SCALE)

Not To Scale



Lakewood
Road



ELWOOD, T.

Officer's Signature

0406

Badge Number