


**New Jersey Police
Crash Investigation Report**

Case Number
2020-00043147

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred on Jack Martin Blvd approximately 100 feet north of the intersection to Route 70.

Driver of Vehicle #1 advised she was in the middle lane of Jack Martin Blvd traveling south towards the intersection of Route 70. Driver #1 advised she looked at her GPS and when looked back at the road, the vehicle in front of her was stopped. Driver #1 advised she struck the rear of Vehicle #2. There was minor damage to the front of Vehicle #1, specifically the chrome piece that has the Chevrolet symbol fell off.

Driver of Vehicle #2 advised she was stopped in the middle lane of Jack Martin Blvd southbound at the red traffic signal for Jack Martin Blvd and Route 70. Driver #1 advised she was struck from behind by Vehicle #1. There was minor scratches to the rear bumper of Vehicle #2.

Vehicle #1 struck the rear of Vehicle #2 which was stopped for the red traffic signal. Driver #1 is the at fault driver for following too closely and distracted from hands free device.

146. Officer's Signature
Brian R Foley

147. Badge #
247

148. Reviewer
Anthony S DeMaio

Badge #
194


149. Case Status
☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00043147

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Brian R Foley

Officer's Signature

247

Badge Number