

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00000894			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Motor vehicle crash was in the center lane on Route 70 Eastbound and Jack Martin Blvd. On arrival, I observed that

Vehicle #1 rear ended Vehicle #2. Vehicle #1 had disabling front end damage. Vehicle #2 had disabling damage to the rear of her vehicle.

Driver #2 stated she was stopping on Route 70 for an ambulance that was crossing Route 70. While she was stopping, she was rear ended by Vehicle #1.

Driver #1 stated he was traveling eastbound when he observed the ambulance crossing Route 70, when did not realize the vehicle in front of him was stopping for the ambulance. He attempted to stop his truck but was not able to stop in time causing him to crash into the rear of vehicle #2.

There were no reported injuries at this time.

After my investigation I found Driver #1 at fault for the crash. Driver #1 was issued a summons for careless

146. Officer's Signature John O Scott	147. Badge # 266	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2021-00000894

145 Crash Description

driving (1506 E21 000070).

John O Scott


266

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00000894

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



John O Scott

Officer's Signature

266

Badge Number