

96	Page 1 of 4		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a							
05	1. Case Number		2020-00021630										10. Crash Occurred On: JACK MARTIN BLVD/RT 70		11. Speed Limit		12. Route No.		13. Milepost		02							
97	2. Police Dept. of		Code		Road Name										Dir		18. Speed Limit		19. To: 17. Cross Road Name/Route No.		118b							
01	Brick Police		01														5 0				05							
98	3. Station/Precinct		25										14		15		16		19. Ramp		119a							
01																					25							
99	4. Date of Crash		5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured		21. Latitude		20. Route Name/Route No.		22. Longitude		119b									
05	0 4 1 0 2 0		Su M Tu W Th Sa		1 6 5 1		1 5 0 6		-		-		-		-		-		119c									
100a	23. Veh. #		24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code								120a									
01	01		933021272		135		02		4534216066		148								01									
100b	26. Driver's First Name		Initial		Last Name		29. Sex		56. Driver's First Name		Initial		Last Name		59. Sex				120b									
04	Kelly		A		Ludwig		F		Samantha		Snyder		F						121a									
101	27. Number & Street		28. City										State		Zip						121b							
02	1989 CAMPBELL RD		Wall										NJ		07719													
102	30. Eyes		DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		122									
05	0 2		D		0		-		NJ		0 4		D		1		-		11									
103	32. Driver's License Number		33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires								123									
01	L 9 0 9 7		4 3 0 6 1		6 2 6 0 2		S 5 9 9 6		6 8 7 6 8		5 3 9 3 4		0 3 1 0 9 3		0 3 2 2 2				08									
104	35. Owner's First Name		Initial		Last Name		65. Owner's First Name		Initial		Last Name								124									
02	☒ Same as Driver		Kelly A		Ludwig		☐ Same as Driver		VW Credit Leasing LTD										04									
105	36. Number & Street		37. City										State		Zip						125							
01	1989 CAMPBELL RD		Wall										NJ		07719						03							
106	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		126a									
04	Mercedes		E350		BK		2008		P60LKT		NJ		Volkswagon		Tiguan		BK		26									
107	44. VIN		45. Expires		74. VIN		75. Expires												126b									
01	W D B U F 8 7 X 3 8 B 3 3 1 6 7 2		06/20		3 V V 2 B 7 A X X J M 0 9 6 6 0 1		03/21												126c									
108	46. Vehicle Removed to:		47. Authority										48. Alcohol Drug Test		49. Hazardous Material		76. Vehicle Removed to:		77. Authority		126d							
01			☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded										☒ No ☐ Yes ☐ Refused		☒ None ☐ On Board ☐ Spill				☒ No ☐ Yes ☐ Refused		126e							
109			☐ Left at Scene ☐ Towed Impounded										Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. - % ☐ Pending		Hazard Class Placard No.		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. - % ☐ Pending		26					
110	48. Alcohol Drug Test		49. Hazardous Material		78. Alcohol Drug Test		79. Hazardous Material												127a									
01	☒ No ☐ Yes ☐ Refused		☒ None ☐ On Board ☐ Spill		☒ No ☐ Yes ☐ Refused		☒ None ☐ On Board ☐ Spill												127b									
111	Type: ☐ Breath ☐ Blood ☐ Urine		Hazard Class Placard No.		Type: ☐ Breath ☐ Blood ☐ Urine		Hazard Class Placard No.												127c									
112	Results: 0. - % ☐ Pending		Hazard Class Placard No.		Results: 0. - % ☐ Pending		Hazard Class Placard No.												127d									
113	50. Carrier No.		51. GVWR / GCWR (trucks & buses only)		80. Carrier No.		81. GVWR / GCWR (trucks & buses only)												127e									
03	☐ USDOT ☒ None		☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		☐ USDOT ☒ None		☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.												26									
114	52. Motor Carrier or Government Entity		53. Motor Carrier or Government Entity																		128							
03																					26							
115	Number & Street		Number & Street																		129							
116																					12							
117	City		State		Zip		City		State		Zip								130									
03																			12									
	135. Damage to Other Property		☐ Yes (If Yes, describe) ☒ No																		131							
																					06							
																					06							
	Oper. 01		136. Charge 39:4-88B										137. Summons No. E20-1555		Oper. 138. Charge		139. Summons No.				133							
																					02							
	Oper. 140. Charge		141. Summons No.										Oper. 142. Charge		143. Summons No.						134							
																					02							
	83		84		85		86		87		88		89		90		91		92		93		94		95		Names & Addresses of Occupants If Deceased, Date & Time of Death	
A	01		01		01		-		59		F		-		-		11		04		-		-		-		Kelly A Ludwig 1989 CAMPBELL RD Wall NJ 07719	
B	02		01		01		-		27		F		-		-		11		04		-		-		-		Samantha Snyder 26 CRESCENT DR Brielle NJ 08730	
C																												
D																												

New Jersey Police Crash Investigation Report												Case Number 2020-00021630			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

V2 was stopped at a red traffic signal in the left-most lane, southbound on Jack Martin Blvd., awaiting the left turn onto Rt. 70 eastbound. V1 was directly behind V2.

On arrival, both vehicles were stopped in the same left turn lane. V1's tires were turned far right. D1 stated she was trying to go straight at the light and she believed the vehicle in front of her (V2) backed into her as she was stopped in traffic. She stated she never moved her vehicle after she stopped in traffic. I advised her she is in the left turn only lane. Once hearing this information, D1 provided a different explanation. She advised was never going straight and she was, in fact, awaiting the left turn.

D2 stated she was stopped at the red traffic signal when V1 struck the rear of her vehicle. She advised she never reversed her vehicle at the time of the crash.

Due to the tires on V1 being left in the right turn position (toward the straight or left turn lane) I found V1 to be at fault and issued summons # E20-1555 for 39:4-88B.

146. Officer's Signature Nicole C Borden	147. Badge # 274	148. Reviewer Joseph L Rossi	Badge # 240	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00021630

145 Crash Description

I advised D1 of my findings on scene and she stated, "Okay."

Nicole C Borden

274

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2020-00021630

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Nicole C Borden

Officer's Signature

274

Badge Number