

96	Page 1 of 4 ☐ Fatal	New Jersey Police Crash Investigation Report	☒ Reportable	☐ Non-Reportable	☐ Change Report	118a
01	1. Case Number 2020-00007077	10. Crash Occurred On: RT 70	11. Speed Limit 5 0	12. Route No. 7 0	13. Milepost - - - -	00
01	2. Police Dept. of Brick Police	Code 01	Road Name W Dir 5 0			00
05	3. Station/Precinct	At Intersection with ☐ Feet ☐ Miles	18. Speed Limit 4 5			25
02	4. Date of Crash mm dd yy 0 2 0 3 2 0	5. Day of Week Su M Tu W Th F Sa	6. Time (use 2400 hrs.) 0 5 4 3	7. Municipality Code 1 5 0 6	8. Total Killed - -	85
01	9. Total Injured - -	19. ☐ To: 17. Cross Road Name/Route No.	21. Latitude - - - - - -			00
04	23. Veh. # 01	24. Policy No.	25. NJ Ins. Code	53. Veh. # 02	54. Policy No. 924988833	120b
02	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☒ Hit & Run	26. Driver's First Name Initial Last Name	29. Sex 00	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run	59. Sex M	121a
02	27. Number & Street	57. Number & Street 604 HARRIS AVE Apt 1				121b
05	28. City	58. City Brielle Borough				122
02	30. Eyes - - DL Class - - Restrictions - - - - Endorsements - -	60. Eyes 0 4 DL Class D Restrictions - - - - Endorsements - -				01
01	32. Driver's License Number	33. DOB mm dd yy	34. Expires mm yy	62. Driver's License Number	63. DOB mm dd yy	123
01	- - - - - -	- - - - - -	- - - - - -	M 1 6 5 0	0 5 2 5 6 1	01
01	35. Owner's First Name Initial Last Name	65. Owner's First Name Initial Last Name				124
01	☐ Same as Driver	☒ Same as Driver Sean McLaughlin				04
01	36. Number & Street	66. Number & Street 604 HARRIS AVE Apt 1				125
00	37. City	67. City Brielle Borough				126a
01	38. Make	39. Model	40. Color	41. Year	42. Plate No.	126b
00	Mini Cooper	Cooper	SL	2010	ZGL35R	00
01	44. VIN	74. VIN				126c
01	- - - - - - - - - -	W M W M L 3 C 5 7 A T X 5 1 4 0 3				00
00	46. Vehicle Removed to:	76. Vehicle Removed to:				126d
00	☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded	☐ Driven ☒ Towed Disabled ☐ Towed Disabled & Impounded				126e
00	☐ Left at Scene ☐ Towed Impounded	☐ Left at Scene ☐ Towed Impounded				26
01	47. Authority	77. Authority				127a
01	☐ Owner ☐ Driver ☐ Police	☐ Owner ☒ Driver ☐ Police				26
01	48. Alcohol Drug Test Given: ☐ No ☐ Yes ☐ Refused	78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused				127b
01	Type: ☐ Breath ☐ Blood ☐ Urine	Type: ☐ Breath ☐ Blood ☐ Urine				48
01	Results: 0. - - % ☐ Pending	Results: 0. - - % ☐ Pending				127c
01	50. Carrier No.	80. Carrier No.				05
04	☐ USDOT ☒ None	☐ USDOT ☒ None				127d
04	☐ MC/MX ☐ None	☐ MC/MX ☐ None				60
04	51. GVWR / GCWR (trucks & buses only)	81. GVWR / GCWR (trucks & buses only)				127e
04	☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.	☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.				26
04	52. Motor Carrier or Government Entity	82. Motor Carrier or Government Entity				128
04	Number & Street	Number & Street				26
04	City	City				129
04	State Zip	State Zip				130
04	135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No					131
04	Oper. 136. Charge	137. Summons No.	Oper. 138. Charge	139. Summons No.		133
04	Oper. 140. Charge	141. Summons No.	Oper. 142. Charge	143. Summons No.		134
04						04

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	00	0	00	00	00	01	00	00	00	0	Hit and Run 0
B	02	01	01	03	58	M	02	05	01	11	11	01	-	Sean McLaughlin 604 HARRIS AVE Apt 1 Brielle Borough 08730
C														
D														

New Jersey Police Crash Investigation Report												Case Number 2020-00007077			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation revealed vehicle 2 collided with the center concrete median on the west side of Rt 70 approximately 200 feet west of Jack Martin Boulevard. After colliding with the median vehicle 1 continued off the roadway to the right and flipped over landing on the driver side of the vehicle.

Ptl. Joaquim #271 was on scene prior to my arrival. Ptl. Joaquim advised he arrived with the driver standing outside the vehicle. The driver climbed out of the vehicle through the front passenger door, which was still open in a vertical position. The driver was bleeding from his forehead and first aid was requested.

Driver vehicle 2 stated he was hit from behind by another vehicle while traveling in the right lane of Rt 70. The force of the rear end impact thrust his vehicle forward causing him to loose control. Vehicle 2 slammed into the center concrete median causing disabling damage to the vehicle. The vehicle continued across both lanes of travel running off the road to the right. The vehicle cart wheeled coming to rest on the drivers side of the vehicle. The roof of the vehicle was damaged indicating the vehicle rolled over at one point. Point Pleasant First Aid provided mutual aid for the crash. Driver vehicle 2 was provided basic first aid but refused to be transported to the hospital for further medical treatment at this time.

I observed paint transfer and scuff marks on the concrete barrier, as well as debris from vehicle 1 covering a large area of Rt 70. Vehicle 2 was facing south on the right shoulder of Rt 70 laying on its side. Extensive

146. Officer's Signature Mark D Storch	147. Badge # 206	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2020-00007077

145 Crash Description

damage was observed to the front end, roof and rear of vehicle 2. The damage to the rear bumper and hatch lid was consistent with driver 1's statement of being rear ended.

A second crash was reported further west on Rt 70 under case number 7076-20. Vehicle 1 of that crash is believed to be the hit and run driver for this crash. The Brick Township Police Department's Traffic Safety Unit will be following up on the investigation.

Detective Walden #162 from the Brick Township Identification Unit responded out to photograph the scene. In addition to the photographs the entire scene was captured by Body-worn cameras.

Mark D Storch


206

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00007077

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Mark D Storch

Officer's Signature

206

Badge Number