

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00010784			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 owner exited his vehicle and walked into Ocean Medical Center (425 Jack Martin Blvd.), leaving his vehicle running in front of the valet booth for a tenant to park. Vehicle 1 then traveled forward into the driver front door of parked Vehicle 2. Vehicle 1 received minor damage to the front bumper and Vehicle 2 received minor damage to the driver side front door. Both vehicles were unoccupied.

Owner of Vehicle 1 stated he knows he put his vehicle in the parked position.

I observed surveillance footage of the accident and determined that the owner of Vehicle 1 did not put the vehicle in the full park position and the vehicle slipped into gear. There were no witnesses on scene.

Owner of Vehicle 1. Donald Bayor NJ DL B09571736307405, phone #732-202-7865


146. Officer's Signature Christopher Robert Newlund	147. Badge # 285	148. Reviewer James L Bartolucci	Badge # 183	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-------------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00010784

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



VALET BOOTH

OCEAN MEDICAL
CENTER
425 JACK MARTIN
BLVD.

Christopher Robert Newlund

Officer's Signature

285

Badge Number